(6)

Name of Work: Maintenance of Water Supply existing Borewells at thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division

GPS Map Camera
Bengaluru, Karnataka, India
3JFM+22R, 3rd Cross Rd, 2nd Phase, Sri Balaji Krupa Layout, RK Hegde Nagar, Bengaluru, Karnataka 560077, India
Lat 13.072617°
Long 77.632618°
14/12/21 03:15 PM GMT +05:30
Google

GPS Map Camera
Bengaluru, Karnataka, India
No.898,2nd Main, 3rd Cross Rd, 2nd Phase, Sri Balaji Krupa Layout, RK Hegde Nagar, Bengaluru, Karnataka 560077, India
Lat 13.071199°
Long 77.632492°
14/12/21 12:06 PM GMT +05:30
Google

ಸಹಾಯಕ ಅಭಿಯಂತರರು
Assistant Engineer
ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬಾಣಸವಾಡಿ ಉಪ ವಿಭಾಗ

Assistant Executive Engineer
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-33

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division

Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division



Google
Bengaluru, Karnataka, India
3J7H+7X7, 1st A Cross Rd, Railwaymen Layout, BDS Layout, Sri Balaji Krupa Layout, RK Hegde Nagar, Bengaluru, Karnataka 560077, India
Lat 13.063096°
Long 77.629259°
20/01/22 10:32 AM GMT +05:30
GPS Map Camera

Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division





Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division

Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division


GPS Map Camera
Bengaluru, Karnataka, India
1325, 10th Cross Rd, Shakti Nagar, 2nd Phase, Sri Balaji Krupa Layout, RK Hegde Nagar, Bengaluru, Karnataka 560077, India
Lat 13.071013°
Long 77.629666°
16/01/22 11:15 AM GMT +05:30
Google
SAMSUNG

GPS Map Camera
Bengaluru, Karnataka, India
3JCJ+PV6, RKH 1st Main Rd, 2nd Phase, Sri Balaji Krupa Layout, RK Hegde Nagar, Bengaluru, Karnataka 560077, India
Lat 13.071712°
Long 77.632104°
11/01/22 11:02 AM GMT +05:30
Google

Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division





ಸಹಾಯಕ ಅಭಿಯಂತರರು
Assistant Engineer
ಬಿ.ಬಿ.ಎಂ.ಪ ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

Assistant Executive Engineer
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪ, ಬಂಗಳೂರು-೨೫

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division





Assistant Engineer

Assistant Executive Engineer
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪ, ಬೆಂಗಳೂರು-24

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division





Assistant Engineer

Assistant Executive Engineer

ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಜಿ.ಬಿ.ಎ., ಬೆಂಗಳೂರು-24

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Heggadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division





Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division

Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division



Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division





Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply existing Borewells at Thanisandra, Hegadenagara Surrounding area in ward no. 06 Byatarayanapura Sub Division



Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner